

Date: February 14, 2000
Distribution: All GE Medical Systems Field Engineers
Product: MR / CT / Xray Mobile Systems

Re: Update to Site Log Direction 2248330.

Overview

A minor update is being issued to the Site Log Book for the following reasons:

1. Elimination of the revision number located on the binder backbone label.
2. Site Information Tab – Page 1, changed wording at bottom of the page to remove the phone number references.

Updated Documentation and Instructions via the web

1. Log into the MR Service Engineering Web Page @
3.87.118.28/optec3/common/serv.htm
2. Perform the security check.
3. Select * Mobile Site Logs
4. Read the down load instructions for the Rev 1 update and down load the update file.
5. Open the down loaded file and print out the pages locally.
6. Perform the upgrade steps in the table.

Location or Tab Name	Remove Pages	Insert Pages
Front Matter	Rev 0 Page B	Rev 1 Page B
Site Information	All blank Rev 0 Page 1-	Rev 1 Page 1-
Remove the Back Bone Label and Title Page from the binder plastic sleeve. Strike through the Rev 0 and mark Rev 1. Re-insert the Back Bone Label and Title page into the binder sleeves.		

Paul C. Senski
Mobile Service Integrator